



Communication	Navigation	Services
CTAF 122.9 APP/DEP 135.25	Elevation 979' TPA 1979'	FUEL: 100LL 24 HR Self-Serve Airport Manager 608-339-3919
	VOR to Field: 117.0 DLL 355°/25 NM	
NOTES: 1. Ultralight activity at airport. 2. Runway 08/26 closed Dec. 1–April 1. 3. Aircraft departing runway 15 requested turn to a heading of 180° after takeoff.		