




| Communication                                                                                                                                                         | Navigation                                            | Services                                                                        |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------|---------------------------------------------------------------------------------|
| CTAF ..... 122.7<br>APP/DEP ..... 120.1                                                                                                                               | <b>Elevation ..... 920'</b><br><b>TPA ..... 1920'</b> | <b>FUEL: NONE</b><br><br><b>Blackhawk Airfield, Inc.</b><br><b>608-839-5155</b> |
|                                                                                                                                                                       | <b>VOR to Field:</b><br>108.6 MSN 106°/7 NM           |                                                                                 |
| <b>NOTES:</b> 1. RUNWAYS 4 & 27 RIGHT TRAFFIC.<br>2. Runway 9: avoid overflight of farm. Track 090 3/4 NM before left turn.<br>3. Deer on and in vicinity of airport. |                                                       |                                                                                 |