

Communication	Navigation	Services
CTAF122.7 APP/DEP135.45 FSS122.1R 117.0T	Elevation 824' TPA 1824'	FUEL: MOGAS, 100LL 24 HR Self-Serve Air Portage 608-742-3300
	VOR to Field: 117.0 DLL 084º/12 NM	

**NOTES:** 1. Large buildings and trees beside runway 35 causes wind shear with strong northwest winds.

- 2. 110' power lines located 1580' south of runway 35
- 3. Runway 04-22 closed Nov. 15 to Apr. 15.